

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representativ	res Present During the Inspection:	
	Vicky S. Miller Environmental Specialist	
OGM	Pete Hess Environmental Scientist III	

Inspection Report

Permit Number:	C0070039		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, March 18, 2008		
Start Date/Time:	3/18/2008 7:45:00 AM		
End Date/Time:	3/18/2008 9:55:00 AM		
Last Inspection:	Tuesday, February 26, 2008		

Inspector: Pete Hess, Environmental Scientist III

Weather: clear, cold; 30's F. InspectionID Report Number: 1586

Accepted by: Jhelfric 77

Tuesday, March 18, 2008

Date

4/10/2008

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	9,471.00
Total Disturbed	51.10
Phase I	
Phase II	
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State ☐ Surface County ☐ Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on March 10, 2008 that the fourth quarter of 2007 surface and ground water monitoring information for the Dugout Canyon Mine permit area had been inserted into the EDI pipeline and was acceptable for uploading into the permanent data base, The Permittee continues to meet this requirement which is a Special Condition of the current State permit (Attachment "Af.

There are no pending compliance actions for this site.

Most of the snowpack on the Dugout Canyon Mine surface facilities has melted off. The access road above the Gilson Well remains impassable due to snow depth.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, March 18, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	V		V	
4.d					
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		<u> </u>		
6.	Disposal of Excess Spoil, Fills, Benches		<u> </u>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation		✓		
14.	Subsidence Control				
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V			
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	V			

Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Tuesday, March 18, 2008

Page 3 of 3

3. Topsoil

The topsoil storage piles for the Soldier Canyon and Dugout Canyon Mine facilities have melted off, with the exception of some snow on the north slopes. The fenced perimeter appears in good repair; all runoff controls are in place and appear to be functioning as designed.

4.a Hydrologic Balance: Diversions

The Permittee has initiated spring cleanup and maintenance procedures for the sites ditches and culvert inlets/outlets and drop grates. The ditch which passes in front of the secondary substation needed minor maintenance to remove cutbank debris from the freeze / thaw cycle. All other diversions which were inspected (some remain snow covered) appeared capable of functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Both the Mine site sediment pond and the waste rock site pond contained water with frozen surfaces. Both impounded volumes were well below the discharge elevation. There were no compliance issues noted.

4.c Hydrologic Balance: Other Sediment Control Measures

Ditches on the east side of the Canyon and the sediment traps associated with them contain frozen snow and ice. Melt water is being directed to the Mine site pond as depicted in the approved mine site drainage control plan.

7. Coal Mine Waste, Refuse Piles, Impoundments

Recently placed volumes of coal processing waste have been spread on the active lift, but are still being compacted. The dozer was idle during today's inspection. There was no non-coal waste visible in the material. There were no indications of spontaneous combustion.

9. Protection of Fish, Wildlife and Related Environmental Issues

Bald eagles were noted in two locations along the Nine Mile Canyon road. Both birds were gathering carrion from the road.

22. Other

A length of 2 inch black plastic pipe was observed on the old exploration road immediately below the impounding embankment of the Mine site sediment pond. The Permittee was asked to remove this pipe and store it inside the Mine facilities area.